

POPPELTON HISTORIC STUDY

B-2582

Block Lot Address
202 88-82 902-914 W. Fairmount Avenue

MAG#0425825934

Approximate age

1800-1845

1845-1860

1865-1880

1880-1896

1896-on

Rating

Architectural

Condition

A	Significant-save	good	fair	poor	bad
B	Quality-Indiv./groups-save	good	fair	poor	bad
C	Important to street/groups	good	fair	poor	bad
D	Insignificant/detrimental	good	fair	poor	bad

Notable features:

Lots 88-82 have had all buildings demolished from them. Several allanthus trees should be saved.


Environmental context:

Trash collection area -- City should clean up. Cars being repaired on the lots with chain and tackle rigged up on large tree. These lots face the narrow Fairmount Avenue which could be a quiet place to live, but a redesign for the entire block is needed to determine what spaces should be used for back-up service and parking for Baltimore Street.




Demolished

B-2582
902-914 W. Fairmount Ave
Block 202 Lots 082-088
Baltimore City
Baltimore West Quad.




B-2582
 902-914 W. Fairmount Avenue
 Block 202 Lots 082-088
 Sanborn Map
 Baltimore City
 Baltimore 1890 vol. 3, Sheet 84_b


Demolished




N. AMITY



STREET



3



STREET

N. POPPLETON 82

B-2582
902-914 W. Fairmount Avenue
Sanborn Maps

DEMOLISHED

